

Scheduled Winter Improvements at The Olde Course at Loveland 2011/2012


5

HOLE # 5

What are the problems with Hole #5?

Planned Improvements

1. Clubhouse parking lot drains onto #5 fairway
2. Elevated water hazard is not visible
3. Drainage problems in fairway
4. Sunken irrigation trenches
5. Buffer from #9 needs improvement
6. Health of #5 green needs improvement
7. Forward tees are not level
8. Hole has in-course out of bounds



Before



After



Artist Rendition of the future Hole #5