



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 001
Southwest Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 002
Southeast Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 003
Northeast Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 004
Northwest Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No.005
View from South



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No.006
View from North



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No.007
View from East



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 008
Southwest Yard Area



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 009
Southeast Site Area



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 010
West Site Area




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 011
Front Porch Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 012
Front Porch Ceiling Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 013
Front Porch Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 014
Front Porch Soffit Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 015
Front Porch Detail




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 016
Front Porch Steps



2007-HA-024 Existing condition
Milner Schwarz House Image No. 017
September 21, 2007 Front Porch Railing



2007-HA-024 Existing condition
Milner Schwarz House Image No. 018
September 21, 2007 Front Porch Detail



2007-HA-024 Existing condition
Milner Schwarz House Image No. 019
September 21, 2007 Front Porch Detail



2007-HA-024 Existing condition
Milner Schwarz House Image No. 020
September 21, 2007 Front Porch Railing



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 021
Rear Porch Ceiling



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 022
Rear Porch Ceiling



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 023
Rear Porch Ceiling Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 024
Rear Porch Ceiling Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 025
Rear Porch Steps



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 026
Rear Porch Slab



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 027
Rear Porch Slab
Edge



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 028
Rear Porch



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 029
Rear Porch Ceiling and Window



2007-HA-024 Existing condition
Milner Schwarz House Image No. 030
September 21, 2007 Rear Door



2007-HA-024 Existing condition
Milner Schwarz House Image No. 031
September 21, 2007 Siding at Rear
Porch



2007-HA-024 Existing condition
Milner Schwarz House Image No. 032
September 21, 2007 Window Elevation



2007-HA-024 Existing condition
Milner Schwarz House Image No. 033
September 21, 2007 Trim Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 034
Cellar Stairs



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 035
Cellar Stairs



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 036
Cellar Stairs Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 037
Cellar Stairs



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 038
Wall Damage at Southeast
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 039
Wall Damage at Front Porch



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 040
Wall Crack



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 041
Foundation Wall Damage



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 042
Wall Damage at Front Porch



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 043
Wall Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 044
Utility Boxes



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 045
Northeast Wall
Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 046
Northeast Wall
Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 047
Northeast Wall
Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 048
Masonry Crack



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 049
Front Door Sill



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 050
Window Sill Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 051
Window Head Detail




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 052
Window Sill Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 053
Window Sill Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 054
Front Door
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 055
Front Porch
Window Elevation




2007-HA-024 Existing condition
Milner Schwarz House Image No. 056
September 21, 2007 Window Head
Detail



2007-HA-024 Existing condition
Milner Schwarz House Image No. 057
September 21, 2007 Window Sill Detail



2007-HA-024 Existing condition
Milner Schwarz House Image No. 058
September 21, 2007 Utility Room
Window Elevation



2007-HA-024 Existing condition
Milner Schwarz House Image No. 059
September 21, 2007 Kitchen Window
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 060
Soffit and Eave Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 061
Soffit and Eave
Detail


2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 062
Not Used



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 063
Soffit and Eave Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 064
Front Porch Soffit & Flashing



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 065
Front Porch Eave Trim Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 066
Front Porch Eave Trim Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 067
Chimney 1 Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 068
Chimney 2 Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 069
Chimney 1 Cap Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 070
Chimney 1 Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 071
Roof Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 072
Roof Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 073
Living Room 105 Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 074
Entry Hall



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 075
Living Room
Closet 106




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 076
Living Room 105
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 077
Entry Hall
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 078
Dining Room 107
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 079
Kitchen 104
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 080
Kitchen 104 Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 081
Kitchen 104 and Storage Room
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 082
Kitchen 104 Elevation




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 083
Kitchen 104 Elevation



2007-HA-024 Existing condition
Milner Schwarz House Image No. 084
September 21, 2007 Bathroom 103
Toilet



2007-HA-024 Existing condition
Milner Schwarz House Image No. 085
September 21, 2007 Bathroom 103
Bathtub



2007-HA-024 Existing condition
Milner Schwarz House Image No. 086
September 21, 2007 Bathroom 103
Shelves



2007-HA-024 Existing condition
Milner Schwarz House Image No. 087
September 21, 2007 Bathroom 103
Bathtub



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 088
Bathroom 103 Sink




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 089
Bathroom 103 Vent



2007-HA-024 Existing condition
Milner Schwarz House Image No. 090
September 21, 2007 Entry 101 Heater



2007-HA-024 Existing condition
Milner Schwarz House Image No. 091
September 21, 2007 Storage Room
102



2007-HA-024 Existing condition
Milner Schwarz House Image No. 092
September 21, 2007 Heater




2007-HA-024 Existing condition
Milner Schwarz House Image No. 093
September 21, 2007 Heater Vent
Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 094
Stair 109
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 095
Stair Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 096
Stair 109
Elevation




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 097
Stair 203
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 098
Bedroom 201 Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 099
Bedroom 202 Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 100
Bedroom 200
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 101
Bedroom 200
Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 102
Bedroom 201




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 103
Bedroom 202



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 104
Basement and Crawlspace Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 105
Basement and Crawlspace Detail



2007-HA-024 Existing condition
Milner Schwarz House Image No. 106
September 21, 2007 Cellar Stairs & Door



2007-HA-024 Existing condition
Milner Schwarz House Image No. 107
September 21, 2007 Cellar Stairs



2007-HA-024 Existing condition
Milner Schwarz House Image No. 108
September 21, 2007 Basement Detail



2007-HA-024 Existing condition
Milner Schwarz House Image No. 109
September 21, 2007 Basement Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 110
Wood Floor Detail (Main Floor)



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 111
Floor Detail (Upper
Floor)



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 112
Floor Detail (Upper
Floor)



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 113
Ceiling Wallpaper Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 114
Inner Wall Blocking Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 115
Wallpaper Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 116
Wallpaper Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 117
Ceiling Rosette Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 118
Plaster Ceiling Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 119
Plaster Ceiling Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 120
Plaster Ceiling
Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 121
Plaster Ceiling
Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 122
Wall Damage (Upper Floor)



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 123
Inner Wall Cavity



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 124
Inner Wall Cavity



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 125
Upper Floor Vent



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 126
Bird Nest



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 127
Door Knob Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 128
Door Knob Detail




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 129
Door Casing & Base Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 130
Door Head Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 131
Door Head Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 132
Door Trim Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 133
Door Trim Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 134
Door Hinge Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 135
Door Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 136
Front Door Transom



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 137
Door Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 138
Door Hinge Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 139
Door Knob Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 140
Door Knob Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 141
Door Hinge Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 142
Door Elevation



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 143
Window Sill Deterioration



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 144
Window Sill Deterioration




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 145
Window Damage



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 146
Casing Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 147
Casing Detail




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 148
Window Damage




2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 149
Window Damage



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 150
Window Damage



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 151
Window Damage



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 152
Window Damage



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 153
Window Sill Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 154
Light Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition
Image No. 155
Light Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 156
Light and Wiring Detail



2007-HA-024
Milner Schwarz House
September 21, 2007

Existing condition Image No. 157
Light Detail